



# PRODUCT CHANGE NOTICE

**PCN Number:** 20-0218C

**Date Issued:** 4/6/2020

**Series:** Connector part numbers with 100 suffix (see list below)

**Part Numbers Affected:** See list below

**Type of Change:** Part number change only, there are no physical changes to the parts

**Change will impact:**      **Form:** No      **Fit:** No      **Function:** No

**Description of Change:** Connector part numbers listed below, having a suffix of 100 will be invalid and replaced with part numbers ending in 000. These parts must now be ordered with the correct suffix of 000.

**Reason for the Change:** The 100-part number suffix was used to identify connectors with high temperature insulators, typically PCT, instead of standard temperature material, typically PBT. All insulator materials used for connectors has been high temperature since 2010, eliminating the need for the 100-part number suffix.

**Effective Date:** 3/15/2020

**Last Time Buy Date:** 3/1/2020

**Last Time Ship Date:** 3/15/2020

**Replacement part number:** See list below

**Date available:** Immediately

**Contact Information:** Contact Mill-Max Sales at [sales@mill-max.com](mailto:sales@mill-max.com) for any questions about this notice.

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.



# PRODUCT CHANGE NOTICE

Discontinued Part Number	Replacement Part Number
104-XX-3XX-41-780100	104-XX-3XX-41-780000
110-XX-XXX-10-003100	110-XX-XXX-10-003000
110-XX-XXX-41-001100	110-XX-XXX-41-001000
110-XX-XXX-41-801100	110-XX-XXX-41-801000
111-XX-XXX-41-001100	111-XX-XXX-41-001000
115-XX-XXX-41-001100	115-XX-XXX-41-001000
115-XX-XXX-41-003100	115-XX-XXX-41-003000
116-XX-XXX-41-006100	116-XX-XXX-41-006000
122-XX-XXX-41-001100	122-XX-XXX-41-001000
134-XX-XXX-00-020100	134-XX-XXX-00-020000
142-XX-XXX-00-591100	142-XX-XXX-00-591000
142-XX-XXX-00-592100	142-XX-XXX-00-592000
150-XX-XXX-00-001100	150-XX-XXX-00-001000
160-XX-XXX-00-001100	160-XX-XXX-00-001000
170-XX-XXX-00-001100	170-XX-XXX-00-001000
210-XX-XXX-41-001100	210-XX-XXX-41-001000
211-XX-XXX-41-001100	211-XX-XXX-41-001000
304-XX-XXX-41-770100	304-XX-XXX-41-770000
310-XX-XXX-41-001100	310-XX-XXX-41-001000
311-XX-XXX-41-001100	311-XX-XXX-41-001000
315-99-103-41-003100	315-99-103-41-003000
315-XX-XXX-41-001100	315-XX-XXX-41-001000
316-XX-XXX-41-003100	316-XX-XXX-41-003000
316-XX-XXX-41-006100	316-XX-XXX-41-006000

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.



MILL-MAX MFG. CORP.  
190 Pine Hollow Road  
Oyster Bay, NY 11771 U.S.A

## PRODUCT CHANGE NOTICE

Discontinued Part Number	Replacement Part Number
322-XX-XXX-41-001100	322-XX-XXX-41-001000
324-XX-XXX-41-002100	324-XX-XXX-41-002000
334-XX-XXX-00-010100	334-XX-XXX-00-010000
334-XX-XXX-00-020100	334-XX-XXX-00-020000
342-XX-XXX-00-592100	342-XX-XXX-00-592000
342-XX-XXX-00-593100	342-XX-XXX-00-593000
342-XX-XXX-00-594100	342-XX-XXX-00-594000
350-XX-XXX-00-001100 *	350-XX-XXX-00-001000 *
350-XX-XXX-00-006100	350-XX-XXX-00-006000
350-XX-XXX-00-107100	350-XX-XXX-00-107000
370-XX-XXX-00-001100	370-XX-XXX-00-000000
399-XX-XXX-00-009100	399-XX-XXX-00-009000
399-XX-XXX-10-003100	399-XX-XXX-10-003000
399-XX-XXX-10-009100	399-XX-XXX-10-009000
410-XX-XXX-41-001100	410-XX-XXX-41-001000
411-XX-XXX-41-001100	411-XX-XXX-41-001000
416-XX-XXX-41-001100	416-XX-XXX-41-001000
416-XX-XXX-41-006100	416-XX-XXX-41-006000
442-XX-XXX-00-591100	442-XX-XXX-00-591000
442-XX-XXX-00-592100	442-XX-XXX-00-592000
450-XX-XXX-00-001100	450-XX-XXX-00-001000
450-XX-XXX-00-006100	450-XX-XXX-00-006000
480-XX-XXX-00-001100	480-XX-XXX-00-001000

*\*Corrected part numbers: P/N's were 350-XX-XXX-00-000100 and 350-XX-XXX-00-000000*

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.



**MILL-MAX MFG. CORP.**  
 190 Pine Hollow Road  
 Oyster Bay, NY 11771 U.S.A

# PRODUCT CHANGE NOTICE

Discontinued Part Number	Replacement Part Number
499-XX-XXX-10-003100	499-XX-XXX-10-003000
499-XX-XXX-10-009100	499-XX-XXX-10-009000
605-XX-XXX-11-480100	605-XX-XXX-11-480000
714-XX-XXX-31-018100	714-XX-XXX-31-018000
800-XX-XXX-10-001100	800-XX-XXX-10-001000
800-XX-XXX-10-002100	800-XX-XXX-10-002000
800-XX-XXX-20-000100	800-XX-XXX-20-000000
800-XX-XXX-62-001100	800-XX-XXX-62-001000
801-XX-XXX-10-001100	801-XX-XXX-10-001000
801-XX-XXX-10-012100	801-XX-XXX-10-012000
802-XX-XXX-10-001100	802-XX-XXX-10-001000
802-XX-XXX-10-002100	802-XX-XXX-10-002000
802-XX-XXX-20-001100	802-XX-XXX-20-001000
802-XX-XXX-61-001100	802-XX-XXX-61-001000
917-XX-XXX-41-005100	917-XX-XXX-41-005000

*4/6/20: Version C – Removed custom part numbers from list.*

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.